

2019 Level 2 Assessment Response Form

RI1592023 - Prudence Island Water District

Required System Operator Classification: D-1

Sanitary Defects

The Sanitary Defects below were identified as part of the August 21, 2019 L2A for RI1592023 - Prudence Island Water District. To protect your public water supply, the following sanitary defects must be corrected by the Due Date below. You are required to Notify RIDOH when each sanitary defect has been corrected. The written response requires, when applicable, photographic evidence of the repairs to the PWS and/or a contractor's invoice. **Authority: 216-RIRC-50-05-1 Rules and Regulations Pertaining to Public Drinking Water.** The Administrative Contact (AC) or Designated Operator (DO), if applicable, must initial the column on the column below once the repairs are made submit a copy this form with the written response and/or photographic evidence.

This office must be notified of any modifications to your system as per 216-RIRC-50-05-1, Sec.1.5. An **Application for Approval** form must be submitted for any planned significant modifications including equipment upgrades and design improvements to your system. Routine maintenance on a water system, such as pipe and valve replacement or repair does not need to be reported.

An **In-Kind Replacement** form must be submitted for replacement of pumps, storage/pressure tanks or treatment components that are functionally equivalent to the original components. Attach an additional sheet if more room is required.

Compliance Schedule and Corrective Action Table

ITEM NO.	Sanitary Defect and Corrective Action	Due Date	Completed Date w/Initials
L2A (6/NWSI/2019) Item #1:	The PWS has been experiencing pressure drops due to line breaks. Since February 5, 2019, the certified operator has conducted work on the service lines nine (9) times. The Certified Operator must be sure to follow the AWWA Standard (C651-14, previously C651-05) when work of this kind is being conducted, especially as this system is not chlorinated. The Certified Operator must revise the Operations and Maintenance Manual (O&M Manual) to include this practice. A copy of the O&M Manual must be submitted by the required due date.	10/11/2019	

L2A (6/NWSI/2019) Item #2:	Review of 2013 video inspection of Indian Spring Well #4 (WL009) that the casing is not properly seated into the bedrock. The gap in this seating allows potentially compromised groundwater from heavy precipitation events or other land use practices at the surface to infiltrate the well. For Indian Spring #4 to continue to be used, the following improvements must occur: 1) provide an internal seal of the casing/bedrock interface and the upper level fractures, to a depth of 80-ft. below ground surface, 2) extend the well casing to a minimum of 30-inches above grade, and 3) undergo comprehensive cleaning, flushing and sanitation (see protocol from 2014 well cleaning). The PWS must provide a corrective action plan (CAP) outlining the steps that will be taken and when they are planned to be completed. These actions must begin once the well is no longer needed at the end of the peak summer season for 2019 and be completed prior to the beginning of the 2020 summer season. If these steps are not to be taken, the PWS will need to determine how to best use Indian Spring #1 (WL008) and the Army Camp Well (WL007) for the 2020 summer season. This determination must be included in the CAP submitted to this office by the due date.	10/11/2019	
L2A (6/NWSI/2019) Item #3:	Note Indian Spring #4 (WL009) vent is fouled with iron oxide solids. The O&M Manual must be revised to include cleaning of the vent screens for all wells on a semi-annual basis in the spring and late summer/early fall months prior to the seasonal wells (Indian Spring 1 and 4) being put into service. This must be submitted by the required due date.	10/11/2019	
L2A(6/NWSI/2019) Item #4:	During the most recent Assessment, it was determined that the Big Blue storage tank (ST001) is primarily being provided water from IS#4. Upon the completion of peak season, the PWS must perform a comprehensive storage and distribution system disinfection and flushing. During this, the PWS must reach a chlorine residual of 0.2 mg/l through the entire distribution system as well as in the Big Blue storage tank. Additionally, the tank must be disinfected in the manner described under AWWA Standard C652-11, Section 4.3 Methods of Chlorination, part 4.3.1-Chlorination Method 1 or 4.3.2-Chlorination Method 2. The PWS must inform RIDOH which disinfection standard will be used. Care should be taken to keep discharge out of surface waters, wetlands, and storm drain systems. This may require the PWS to follow the field dechlorination standards found in AWWA C655-18. Once this is complete, the PWS must submit the daily logs to this office showing that the 0.2 mg/l chlorine residual was maintained throughout the distribution system, as well as a revised copy of the O&M Manual outlining the adopted practice.	10/11/2019	
L2A (6/NWSI/2019) Item #5:	As part of the trigger notice that was mailed on August 5, 2019, the PWS was required to submit a daily disinfection log by August 29, 2019. This office has not received this data and is requesting it be submitted by the due date.	9/23/2019	

L2A (6/NWSI/2019) Item #6:	The PIWD must provide reasoning for maintaining the Bristol Colony Well (WL001). This well has a capacity of less than 3 gallons per minute and has not been used since 2008. Allowing this well to remain physically connected to the PIWD allows for potential cross-connection contamination of the system due to long term stagnation. If the PIWD is unable to provide a valid reason that is agreeable with this office, the well must be physically disconnected and properly decommissioned.	9/23/2019	
---	--	-----------	--

I certify that the above information is accurate.

Name of PWS

Owner/Representative:

(Please Type or Print)

Date

PWS Owner/Representative:

(Signature)

If this form is not signed, the Level 2 Assessment will not be considered complete

SYSTEM OVERVIEW

System Operator Classification: D-1

William Capron, System Operator

GENERAL:

The Prudence Island Water District (PIWD) community water system is located on Prudence Island and is serving approximately 350 service connections. As many homes on the island are vacation/weekend homes, and there is no census data available, it is determined that the average number of people served by PIWD is 608 persons.

Total water produced by the PIWD for the year 2017 is 6.7 million gallons with an average of 17,956 gallons per day (gpd). PIWD is an un-metered system so it is not possible to determine if there are leaks. During the off season, at least 240 service connection are "winterized".

SOURCES:

Army Well (AKA Harris Well) is located on Army Road. This 6-inch (in.) diameter well is drilled to a depth of 291-feet (ft.) and extends 30-in. above grade. This well has a Goulds submersible 2 hp pump with a rated capacity of 3-11 gpm (varies depending on the time of year). This well is presently used as the primary source.

Indian Springs Wells #1 & 4, and the Bristol Colony Well are considered the backup sources of water supply for the system.

Indian Springs Well # 1 (summer use) is located off Homestead Avenue east of Mill Creek. This 6-in. diameter well drilled to a depth of 467-ft extends about 3 ft above grade and is located in a wooden box with a slanted roof wooden cover. This well has a Goulds Model # 10GS15-412C 2 hp submersible pump with a rated capacity of 22 gallons per minute (gpm) placed approximately 140 ft below ground surface (bgs). This well was taken out of service and surged to increase production in 2013.

Indian Springs Well # 4 (summer use) is located off Homestead Avenue 15 ft east of Mill Creek. This 6 in diameter well is drilled to a depth of 438 ft, extends 15 in above grade and is located in a wooden box with a slanted wooden cover. The pump for this well was replaced in 2019 with a Goulds 35-GS20.

Bristol Colony Well (aka Broadway-DeWitt) (back-up) is a 6-in. diameter, 105 ft deep well extends 18 in. above the 5 ft deep cement vault with a cement metal-rimmed cover. This well is equipped with a submersible pump, a new flow totalizer with a restrictor capacity of 3 gpm. This well was to be placed on inactive status and testing would be discontinued but it was not to be abandoned.

The following wells are no longer being utilized:

Broadway Well # 1 is not in use. Survey 1996 response stated that this well had been disconnected from the system and further correspondence dated 3/12/97 stated that the Broadway Well was to be placed on inactive status and testing would be discontinued but it was not to be abandoned.

Indian Springs Dug Well has been physically disconnected from the system.

Goulet Well is not in use and is physically disconnected. Correspondence dated 3/12/97 stated that this well has been deactivated with all equipment and structures removed. Ownership of this well has been transferred to the Prudence Island Water District.

Navy Well is owned by RIDEM and was at one time leased on a 20-year basis to Prudence Island Utility Corporation (owner of the PWS prior to the creation of the PIWD in 2004). The lease had expired prior to PIWD purchase of the PWS and the PIWD has no intention to renew the lease.

Source ID	Facility Name	Local Name	Type	Availability
WL001	Wl-Bristol Colony	BC WELL	WL	E
WL007	Wl-Army Well	Army Well	WL	P
WL008	Wl-Indian Spring #1	IS#1	WL	S
WL009	Wl-Indian Spring #4	IS#4	WL	S

Type: WL=Well CC=Consecutive Connection

Availability: P=Permanent E=Emergency S=Seasonal I=Interim O=Other

TREATMENT:

This PWS currently has no treatment.

STORAGE:

In 2003 a 100,000 gallon vertical, cylindrical atmospheric tank was constructed. The overflow for this tank is at 149 ft. mean sea level elevation and the tank discharges via a below grade valve vault (also constructed in 2003). Also, located within the Broadway Booster Station are two Well-X-Trol WX-350 pressurized storage tank. These tanks operate in conjunction with the Army Well.

Storage ID	Facility Name	Local Name	Storage Type	Construction Material	Comments
ST001	St-Storage Tank 1	BIG BLUE	Reservoir	Steel	100,000 GAL RESERVOIR STORAGE TANK, LOCATED ON ROGER WILLIAMS LN BETWEEN SUNSET HILL AVE AND ALLENS LN. OVERFLOW ELEVATION IS 149 FT ABOVE MEAN SEA LEVEL. BOLTED CARBON STEEL PLATES AND GLASS FUSED.
ST002	St-Storage Tank 2	AMTROL WELL XTROL WX-350 (2)	Hydro pneumatic	Steel	TWO WELL XTROL WX-350 TANKS LOCATED ON BROADWAY

PUMPS/PUMP FACILITIES:

Broadway Booster Station houses an Aeromotor 1 hp centrifugal pump with a 5 gpm capacity and a Burkes 1 hp centrifugal pump with a 5 gpm capacity. These pumps operate in a lead/lag operation; the lead pump comes on at 41 psi and off at 52 psi 2nd pump comes on at 38 psi and off at 52 psi.

DISTRIBUTION:

PIWD distribution system is located on the eastern side of the island. It extends as far south as the Broadway vicinity and as far north as Warner and Raphael Ave.

OTHER:

A new 40 kW, 440 volt, 3 phase propane generator is in place at the Indian Spring Well Site. A new 13 kW, 210 volt, single phase propane generator is in place at the Army Camp Well Site.

Inspector: Garth Hoxsie-Quinn

PWS Name: Prudence Island Water District

BRISTOL COLONY

- 1 How is the well used (5.f).
It is being recommended that the Bristol Colony Well (WL001) be physically disconnected from PIWD. This well has a capacity for less than 3 gallons per minute and has not been used since 2008. Allowing this well to remain physically connected to PIWD allows for potential cross-contamination of the system due to long term stagnation. PIWD must provide sound reasoning for why the Bristol Colony Well (WL001) should remain connected to the system.
Primary
Backup
Emergency
Not a PWS
Not Drinking Water
True
- 2 Note the height of the well in the Comments Section (5.k).
In a pit
- 3 The sanitary seal/well cover are intact with gasket and tight bolts. (5.a)
- 4 The electrical conduit is secured (5.b).
- 5 The exposed portion of the well is structurally sound, shows no signs of deterioration (5.l). Note findings in Comments Section.
- 6 The well cap is vented and screened with the screen facing downward (5.c).
- 7 The well cover was removed to inspect the gasket and ensure no insects. Describe findings in the comments section (5.g).
- 8 The well was disinfected following the Well/System Disinfection Procedure provided by RIDOH after well cover removed (5.h). If not, note when disinfection will occur in the comments section.

9 There are no unprotected cross-connections at the well head (5.i).

L2A (6/NWSI/2019) Item #6: The PIWD must provide reasoning for maintaining the Bristol Colony Well (WL001). This well has a capacity of less than 3 gallons per minute and has not been used since 2008. Allowing this well to remain physically connected to the PIWD allows for potential cross-connection contamination of the system due to long term stagnation. If the PIWD is unable to provide a valid reason that is agreeable with this office, the well must be physically disconnected and properly decommissioned.

10 There is no evidence of standing/ponding water around or near the well (5.n).

11 The well head area is secured to prevent unauthorized access (5.o).

12 There have been no spills in the vicinity of the well that may contaminate the source (5.p).

ARMY WELL

- 1 How is the well used (5.f).
Primary
Backup
Emergency
Not a PWS
Not Drinking Water
True
- 2 Note the height of the well in the Comments Section (5.k).
24-inches
- 3 The sanitary seal/well cover are intact with gasket and tight bolts. (5.a)
- 4 The electrical conduit is secured (5.b).
- 5 The exposed portion of the well is structurally sound, shows no signs of deterioration (5.l). Note findings in Comments Section.
- 6 The well cap is vented and screened with the screen facing downward (5.c).
- 7 The well cover was removed to inspect the gasket and ensure no insects. Describe findings in the comments section (5.g).

Inspector: Garth Hoxsle-Quinn

8 The well was disinfected following the Well/System Disinfection Procedure provided by RIDOH after well cover removed (5.h). If not, note when disinfection will occur in the comments section.

10 There is no evidence of standing/ponding water around or near the well (5.n).

11 The well head area is secured to prevent unauthorized access (5.o).

12 There have been no spills in the vicinity of the well that may contaminate the source (5.p).

9 There are no unprotected cross-connections at the well head (5.i).

INDIAN SPRING #1

1 How is the well used (5.j).

Primary

Backup

Emergency

Not a PWS

Not Drinking Water

2 Note the height of the well in the Comments Section (5.k).

3 The sanitary seal/well cover are intact with gasket and tight bolts. (5.a)

4 The electrical conduit is secured (5.b).

5 The exposed portion of the well is structurally sound, shows no signs of deterioration (5.l). Note findings in Comments Section.

6 The well cap is vented and screened with the screen facing downward (5.c).

7 The well cover was removed to inspect the gasket and ensure no insects. Describe findings in the comments section (5.g).

8 The well was disinfected following the Well/System Disinfection Procedure provided by RIDOH after well cover removed (5.h). If not, note when disinfection will occur in the comments section.

PWS Name: Prudence Island Water District

10 There is no evidence of standing/ponding water around or near the well (5.n).

11 The well head area is secured to prevent unauthorized access (5.o).

12 There have been no spills in the vicinity of the well that may contaminate the source (5.p).

9 There are no unprotected cross-connections at the well head (5.i).

INDIAN SPRING #4

1 How is the well used (5.j).

Indian Spring #4 (WLO09) is used as a peak seasonal supply.

Primary

Backup

Emergency

Not a PWS

Not Drinking Water

2 Note the height of the well in the Comments Section (5.k).

This well is currently 15-inches above grade. It is being required that the top of this well be raised to at least 30-inches above grade.

3 The sanitary seal/well cover are intact with gasket and tight bolts. (5.a)

4 The electrical conduit is secured (5.b).

Inspector: Garth Hoxsie-Quinn

6 The exposed portion of the well is structurally sound, shows no signs of deterioration (5.f). Note findings in Comments Section.

L2A (6/NWSI/2019) Item #2: Review of 2013 video inspection of Indian Spring Well #4 (WL009) that the casing is not properly seated into the bedrock. The gap in this seating allows potentially compromised groundwater from heavy precipitation events or other land use practices at the surface to infiltrate the well. For Indian Spring #4 to continue to be used, the following improvements must occur: 1) provide an internal seal of the casing/bedrock interface and the upper level fractures, to a depth of 80-ft. below ground surface, 2) extend the well casing to a minimum of 30-inches above grade, and 3) undergo comprehensive cleaning, flushing and sanitation (see protocol from 2014 well cleaning). The O&M must provide a corrective action plan (CAP) outlining the steps that will be taken and when they are planned to be completed. These actions must begin once the well is no longer needed at the end of the peak summer season for 2019 and be completed prior to the beginning of the 2020 summer season. If these steps are not to be taken, the PWS will need to determine how to best use Indian Spring #1 (WL008) and the Army Camp Well (WL007) for the 2020 summer season. This determination must be included in the CAP submitted to this office by the due date.

6 The well cap is vented and screened with the screen facing downward (5.c).

L2A (6/NWSI/2019) Item#3: Note Indian Spring #4 (WL009) vent is fouled with iron oxide solids. The O&M Manual must be revised to include cleaning of the vent screens for all wells on an semi-annual basis in the spring and late summer/early fall months prior to the seasonal wells (Indian Spring 1 and 4) being put into service. This must be submitted by the required due date.

7 The well cover was removed to inspect the packet and ensure no insects. Describe findings in the comments section (5.g).

8 The well was disinfected following the Well/System Disinfection Procedure provided by RIDOH after well cover removed (5.h). If not, note when disinfection will occur in the comments section.

9 There are no unprotected cross-connections at the well head (5.j).

10 There is no evidence of standing/ponding water around or near the well (5.n).

11 The well head area is secured to prevent unauthorized access (5.o).

12 There have been no spills in the vicinity of the well that may contaminate the source (5.p).

DISTRIBUTION SYSTEM

PWS Name: Prudence Island Water District

1 Water system pressure is being maintained above 20 psi (1.a)?

L2A (6/NWSI/2019) Item #1: The PWS has been experiencing pressure drops due to line breaks. Since February 5, 2019, the certified operator has conducted work on the service lines nine (9) times. The Certified Operator must be sure to follow the AWWA Standard (C651-14, previously C651-05) when work of this kind is being conducted, especially as this system is not chlorinated. The Certified Operator must revise the Operations and Maintenance Manual (O&M Manual) to include this practice. A copy of the O&M Manual must be submitted by the required due date.

2 The water system has not experienced pressure drops lower than the usual operating pressure (1.b). If it has, state when and why in comments.

3 There been no fire fighting events, flushing operations or sheared hydrants (1.c) if yes, state when in comments. System wide flushing operations - March/April 2019 Does the system have a current flushing program (less than 10 years old).

4 There have been no pipe or main breaks (1.d). If there have, when and where. See Item 1 above.

5 Recent plumbing/fixture repairs or additions have been installed properly to avoid introducing total coliforms into the system. List any improvements in the comments section (1.e)

Replaced the diaphragm valve after water meter at Indian Spring (IS) in June 2019. This was sanitized, no bacterial sample were collected. Additionally, the pump for Indian Spring #4 (WL009) was replaced on June 10, 2019. This was sanitized, bacteria samples were collected, analyzed and came back absent.

6 There has been no vandalism and/or unauthorized access to the system (1.f).

7 The system is secured to deter unauthorized access (1.g)?

Indian Spring (IS) wells do not have locks. The PWS can choose to install well covers that allow for a locking mechanism (must still be properly bolted) or can continue to use the existing well covers provided that they are durable covers with stainless-steel bolts and downward facing vents that are screened with #24 mesh.

8 There is no evidence of intentional contamination within the distribution system (1.h).

9 There are no visible indicators of unsanitary conditions or potential sources of contamination (1.i).

10 There are no signs of sanitary defects in the pump house. If there are defects, list them in the comments section (1.j)

11 State in the comments field the last time the pumps were serviced (1.k)

Indian Spring #4 (WL009) pump replaced 6/10/2019

Inspector: Garth Hoxsie-Quinn

PWS Name: Prudence Island Water District

12	There have been no new inactive/back up wells but into service (1.i). Indian Spring #1 WL008) was last used in 2017 and Bristol Colony well (WL001) was last used in 2008.	✓	22	Provide the date of the most recent TC absent sample collected (1.v). Date July 14, 2019	✓
13	There are no hydrants, meters or blow offs located in an area with a high water table (1.m)	✓	24	The PWS monitors the seasonal shutdown process of individual service connections.	✓
14	The Public Water System has a current, enforceable cross connection control policy with list of high risk connections (1.n). The PWS is currently conducting a cross-connection survey that is to be completed by 8/1/2020.	✓	23	Provide additional comments in the Comment Box.	
15	The Public Water System has high risk sites certify that backflow is tested on an annual basis (1.o). Every single connection will have backflow device by 8/1/2020.	✓	STORAGE TANK 1		
16	The Public Water System had no trouble achieving a chlorine residual at the ends of the distribution system while disinfecting (1-p). L2A(6/NWSJ/2019) Item #4 - During the most recent Assessment, it was determined that the Big Blue storage tank (STD001) is primarily being provided water from IS#4. Upon the completion of peak season, the PWS must perform a comprehensive storage and distribution system disinfection and flushing. During this, the PWS must reach a chlorine residual of 0.2 mg/l through the entire distribution system as well as in the Big Blue storage tank. Additionally, the tank must be disinfected in the manner described under AWWA Standard C652-11, Section 4.3 Methods of Chlorination, part 4.3.1-Chlorination Method 1 or 4.3.2-Chlorination Method 2. The PWS must inform RIDOH which disinfection standard will be used. Care should be taken to keep discharge out of surface waters, wetlands, and storm drain systems. This may require the PWS to follow the field dechlorination standards found in AWWA C655-18. Once this is complete, the PWS must submit the daily logs to this office showing that the 0.2 mg/l chlorine residual was maintained throughout the distribution system, as well as a revised copy of the O&M Manual outlining the adopted practice.	✓	1	The vents are turned down with an appropriate air gap and/or are screened and in good condition (4.e).	✓
17	There have been no analytical results or additional samples collected, including the source samples, which were positive (not for compliance) (1.q).	✓	2	The tank overflow is screened with an appropriate air gap (minimum of 12 inches), and is in good condition (4.g).	✓
18	There were no other water quality parameters measured that were out of the ordinary. If there were, please list in the comments section (1.r). Field measurements for conductivity, results normal.	✓	3	The access opening for the finished water storage tank has a proper gasket and seal (4.c)(N/A for small pressurized maintenance storage tanks)	✓
19	There have been no community illness outbreaks suspected of being waterborne (1.s).	✓	5	The facility is secured to prevent unauthorized access of finished water storage (4.b).	✓
20	The water system has not received a Level 1 Trigger within the past 12 months (1.i). This is the 6th Level 2 Assessment since October 2017. As a result, the PWS is under a consent order to install backflow prevention devices on all service connections by August 1, 2020.	✓	6	The storage facility is sealed with screened vents, locked doors etc (4.p). List any unsealed openings in the comments section.	✓
21	The Public Water System has been required to perform disinfection after correcting deficiencies that introduced Total Coliforms in the past 12 months (1.u). August 2019	✓	7	There were no observed leaks (4.a.)	✓
		✓	8	There were no observed physical deterioration of the tank that could contribute to the source of contamination (4.d).	✓
		✓	12	The tank can be isolated from the water system (4.n).	✓
		✓	13	There has been no facility maintenance that could have introduced contamination. If so, note when in the comments (4.j) The 100,000 gal. (Big Blue) tank is in very good condition with NO indication of any leaks, a PAX water recirculation system was installed in January 2019. Is maintenance documented	✓
		✓	14	There is no evidence of intentional contamination at the storage tank (4.m).	✓
		✓	STORAGE TANK 2		

Inspector: Garth Hoxsie-Quinn

PWS Name: Prudence Island Water District

- 3 The access opening for the finished water storage tank has a proper gasket and seal (4.c)-(N/A for small pressurized maintenance storage tanks)
- 5 The facility is secured to prevent unauthorized access of finished water storage (4.b).
- 6 The storage facility is sealed with screened vents, locked doors etc (4.p). List any unsealed openings in the comments section.
- 7 There were no observed leaks (4.a.)
- 8 There were no observed physical deterioration of the tank that could contribute to the source of contamination (4.d).
- 9 The pressure tank is maintaining a minimum pressure of greater than 20 psi (4.h).
Pressure bladder tanks at Broadway pump house. 30-50 psig.
Pressure range

- 10 The pump control switch does not immediately activate when there is demand on the system (4.i)
- 11 The tank drain has an appropriate air gap (minimum of 12 inches), and is in good condition (4.r).
- 12 The tank can be isolated from the water system (4.n).
- 13 There has been no facility maintenance that could have introduced contamination. If so, note when in the comments (4.j)
Well house and Broadway pump house in good physical condition.
Is maintenance documented
- 14 There is no evidence of intentional contamination at the storage tank (4.m).

- 1 The PWS has a standard operating procedure that is used in conjunction with the RIDOH Well Disinfection Procedure for disinfecting the well and distribution system.
L2A (6/NW51/2019) Item #5: As part of the trigger notice that was mailed on August 5, 2019, the PWS was required to submit a daily disinfection log by August 29, 2019. This office has not received this data and is requesting it be submitted by the due date.

- 1 There was no heavy rainfall prior to the sample being collected (2.a)
- 2 There has been no flooding/pooling of water, or, no rapid snow melt in the vicinity of the well (2.b).
- 3 There have been no observed changes in availability of source water (2.c).
- 4 There has been no interruption in power (2.d).
Generator did activate on July 4th; no loss of power.
- 5 There have been no periods of extreme heat or extreme cold (2.e).

- 1 The PWS has an approved Coliform Sampling Site Plan (3.c).
- 2 The sample tap is in good condition (3.a).
The primary distribution tap and upstream/downstream taps are all secure dedicated taps within locked enclosures at the POE and at each residence.
Tap Location
What is the primary use?
The sample tap is properly identified on the Coliform Sampling Plan (3.d).
Primary (RTOR) Sample
Repeat Original (RPOR)
Repeat Other (RPOI)
- 3 There have been no plumbing changes at the site of the Total Coliform presence sample. If yes, not what work was done and when in the comments section (3.f).
- 6 There have been no low pressure events at the service connection of the Total Coliform presence (3.j).
- 8 There are no observed cross-connections after the survey connections. If there are, list in the comments field (3.h).

Inspector: Garth Hoxsie-Quinn

9 The PWS is using an adequate sample site. If the boxes below are checked, then consider this as a Sanitary Defect. (3m-a)

Sample tap swivels

Sample tap does not have separate hot/cold valves.

10 The sampler followed the proper sample protocol(3.o-e)

Aerator was not removed.

Sample tap was not properly sanitized.

Sample tap was not properly flushed (3-5 mins).

Sample containers were not properly sanitized when acquired from the lab.

Sample containers were not properly stored, packed and transported.

5 All back-flows present are working, have been tested and tagged (3.i).

7 There are no treatment devices after this service connection (3.k).

PWS Name: Prudence Island Water District

9 There were no anomalies observed on the settled water turbidity (5g).

10 There were no observed cross-connections at the treatment process. If there were, list them in the comments field (5.k).

11 List the treatment type, note if Point of Entry (POE) or Point of Use (POU). Please note in comments. (5l)

12 Maintenance is occurring and being properly documented. Note the last time system was maintained in the comments field (5.m).

13 There have been no recent repairs made to treatment system (5.n).

TREATMENT PLANT INDIAN SPRING WELLS

1 There have been no interruptions in the treatment process (5.a). If so, note when in the comments section.

2 The treatment devices are online and being maintained (5.b).

3 There has been no installation of treatment without approval from RIDOH (5.c).

4 There have been no changes made to the treatment process (addition of a process, changes in chemical or dosage). Note all observed changes in the comments field.(5.d).

5 What is the Free Chlorine Measurement down stream of the application point?(5f)

6 Review of the filter turbidity profiles revealed no anomalies. (5g)

7 The PWS has been able to maintain Contact Time (CT) calculations (5h)

8 The flow rates were at the rated capacity?(5i)