




## Pole Plot – Common Joints




## Pole Plot – Macrojoints



## Pole Plot – Fault Planes




## Pole Plot – Foliation/Cleavage







## Pole Plot – Quartz Filled Joints, Veins and Fractures




## Pole Plot – Gash Veins and Fractures




## Rose Diagram – Common Joints




## Rose Diagram – Macrojoints




## Rose Diagram – Fault Planes




## Rose Diagram – Foliation/Cleavage



## Rose Diagram – Bedding



## Rose Diagram – Quartz Filled Joints, Veins and Fractures



## Rose Diagram – Gash Veins and Fractures

